

Measurement Report

| | |
|-----------------------------|-----------------------------|
| Name: | Result13809 |
| Date & Time: | 2/23/2022 1:20:44 PM |
| Task name: | MT12-MM verification tool |
| Device SN, Fixture SN: | Manta-W+ 72002, not defined |
| Verification tool SN: | 670026A |
| Connector ID: | |
| Customer: | |
| Technician: | Viktoria |
| Company: | Sumix |
| Polarity type for checking: | Type A |

PASS

| | | | | | | | | | | | | |
|-----------------|---|---|---|---|---|---|---|---|---|----|----|----|
| Side A | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Side B expected | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Side B actual | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |

2/23/2022 1:20:44 PM

Measured with MaxInspect DEV-2383-b879f3a2